







	TRUE	REPORT
		ZYX10-2169010
Auction		USS NIIGATA
Auction date		2024-02-14
Lot number		2052
Frame		ZYX10
Brand		TOYOTA
Model		C-HR
Milage		66,500 km
Displacement		1800 сс
Year		2019
Grade		G MODE NERO
Equipment		AAC
Transmission		FAT
Color		WHITE-2 TONE
Score		4.5
Status		SOLD
Powered By		TRUEREPORT JP

Auction list explanation

- 1. A1 Small Scratch
- 2. A2 Scratch
- 3. A3 Big Scratch
- 4. E1 Few Dimples
- 5. E2 Several Dimples
- 6. E3 Many Dimples 7. U1 Small Dent
- 8. U2 Dent
- 9. U3 Big Dent
- 10. W1 Repair Mark/Wave (hardly detectable)
- 11. W2 Repair Mark/Wave
- 12. W3 Obvious Repair Mark/Wave (needs to be repainted)
- 13. S1 Rust
- 14. S2 Heavy Rust
- 15. C1 Corrosion
- 16. C2 Heavy Corrosion
- 17. P Paint marked18. H Paint fadedX Need to be replaced
- 19. XX Replaced
- 20. B1 Small dent with scratch (size like a thumb)
- 21. B2 Dent with scratch (size like flat of the hand)
- 22. B3 Big Dent with scratch (size like elbow)23. Y1 Small Hole or Crack
- 24. Y2 Hole or Crack
- 25. Y3 Big Hole or Crack X1 Small Crack on Windshield (approximately 1cm)
 26. R Repaired Crack on Windshield RX Repaired Crack on Windshield (needs to be replaced)
- 27. X Crack on Windshield (needs to be replaced)
- 28. G Stone chip in glass













